2023

PERSONAL WATERCRAFT AND JET BOATS

*** NOTE *** ALL UNITS WILL HAVE BILGE PLUGS REMOVED ***
Basic PWC/Jet Boat winterization includes: Flush engine with bio
antifreeze throughout system, stabilize fuel, fog down cylinders,
torque trailer lugs, grease buddy bearings.

Units with fresh water systems or ballast bags require additional anti-freeze and labor charges if requested. Shrink Wrap and Winter storage available for all service customers Basic Trailer light repairs done on hourly basis plus parts needed

YAMAHA PWC JET BOAT 10 HOUR SERVICE

Change engine oil and filter, inspect exhaust fasteners, hoses, impeller wear ring clearance, Pump mounts, steering cable & bushings, Supercharger clutch(if applicable), Air intake silencer, EMS sensor, Cut off switch, Monitor beeper, coolant, fault codes, gate backlash, Locking sleeve, connecting arms & bushings. Reset service maintenance.

Winterize ballast bags: \$45.00 Labor plus 1 or 2 antifreeze as required

Winterize Fresh water systems: \$30.00 Labor plus 2 gal antifreeze

Winterize Live wells: \$15.00 Labor plus 1 gallon antifreeze

INBOARD SKI BOATS

Basic winterization Program 1 \$ 214.00 Labor, plus materials: fogging oil & stabilizer \$15.95 showers, water and balast systems on a per boat basis. Antifreeze 4 gallons at \$19.95 per gallon.

ACCESSABILITY BEYONE NORMAL IS AN ADDITIONAL CHARGE PER BOAT BASIS, SUCH AS CRUISERS, INBOARDS OR HARD TO ACCESS ENGINE COMPARTMENTS

I/O STERN DRIVE BOATS AND OUTBOARDS

Basic boat-outboard winterizations include: Running engine, adding stabilizer to fuel system, fogging down cylinders, flush block and cooling system, torque wheel lugs, grease buddy bearings.

Wet premium winterizations are available. Big block engines require 7 to 9 quarts of oil. Basic winterization DOES NOT INCLUDE fresh water systems, ballast, livewells, heat, AC or holding tanks; quoted per boat basis. All bravo drives require BIO ANTIFREEZE which in included in the big block programs. Basic Trailer light repairs done on a per hour basis plus parts required.

WE CANNOT DO HOLDING TANKS: SHOULD BE EMPTIED BEFORE WINTERIZATION